

## MX150 Only!

### Introduction

According to AptioFixPkg's README, "[c]ertain firmwares fail to properly initialize 0xE2 MSR register (MSR\_BROADWELL\_PKG\_CST\_CONFIG\_CONTROL) across all the cores....

CFG Lock option is available on most APTIO V firmware, although it may be hidden from the GUI. If VerifyMsE2 reports that your 0xE2 register is consistently locked, you may try to unlock this option directly."

### How to Unlock

Cyb and FallenChromium created script to unlock. Please download DVMT\_and\_0xE2\_fix and read README to unlock.

After that, you should delete OC MSR 0xE2 patch.

Open /EFI/OC/config.plist, change the following code:

```
<key>AppleXcpmCfgLock</key>  
- <true/>  
+ <false/>
```

### Credits

- Acidanthera
  - AptioFixPkg
  - OpenCorePkg
- Cyb and FallenChromium